Oil Field Environmental Incident Summary

Responsible Party:

Well Operator: OXY USA INC.

Well Name: STATE HECKER 1-2-11H-142-98

Field Name: WILLMEN Well File #: 21897

Date Incident: 6/13/2012 Time Incident: 2315 Facility ID Number:

County: BILLINGS Twp: 143 Rna: 98 Sec: 35 Qtr: SE SE

Location Description:

Submitted By: Terry Ryland Received By:

Contact Person: Terry Ryland

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** Oil 0 barrels 0 barrels 0 barrels **Brine** 0 barrels 0 barrels 0 barrels Other 18 barrels 17 barrels 17 barrels

Description of Other Released Contaminant:

Fresh water with fracing chemicals.

Inspected: Written Report Received: 1/8/2013 Clean Up Concluded: 6/14/2012

Risk Evaluation:No immediate risk.

Areal Extent:

Potential Environmental Impacts:

Surface soil only.

Action Taken or Planned:

Wylie Bice responded to the spill with a vacuum truck and picked up 17 barrels of liquid and took to their Bullinger SWD for disposal.

Wastes Disposal Location: Bullinger SWD

Agencies Involved:

Updates

Date: 6/18/2012 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

NDIC retains oversight.